

#### Officers:

Larry Borton President

Dick Best Vice President

Steve Harsh Treasurer

Stephen Colby Secretary

#### **Board of Directors:**

Mark Coucke (2-year Term)
Chet Dawson
Frank Eastman
Dave Oxendale (2-year Term)
John Yurkon

## Bookkeeper/Membership Coordinator:

Dick Best 517-351-4675 517-285-6688

#### **Maintenance Manager:**

Chet Dawson 517-339-3727 517-449-2182

#### **Maintenance Assistant:**

Steve Ballbach 517-331-4390

#### **Newsletter Editor:**

Dick Best

## **The Monthly Flyer**

November-December 2021 Vol. 76 No. 11-12

# BOARD APPROVES AVIONICS UPGRADES

At the December meeting, the board approved purchasing a Garmin GFC 500 Digital Autopilot for the Archer and upgrading the Skyhawk 430 WAAS GPS navigator to a Garmin GTN 650 xi which will match the new GPS in the Archer, thus keeping the NAV/COM features in both planes the same. Beacon Aviation in Grand Ledge submitted the wining proposal which includes a substantial discount for doing both projects.

Neither of these projects will be happening right away. Garmin is experiencing supply chain problems. The equipment has been ordered but the autopilot parts are not scheduled to arrive until February18th, while the Skyhawk parts are scheduled for June 28th. Beacon is ready to go when the parts arrive.

The autopilot has amazing features including the blue LVL button which will right the plane from an unusual attitude and the Smart Glide button which will glide the plane to a nearby airport in the event of an engine failure. Read all about it here: https://



## **BOARD MEETING**

Thursday, January 20th, 6 PM (1800)
ZOOM Meeting link will be emailed
All members encouraged to attend

## Pilot's Tip of the Week

## Activating an Approach

"Can you explainthe difference betweenloading and activating an approach in a GPS? I know this is a common area of confusion"—Joe M.

Doug Stewart replies:

"The first step in removing the veil of confusion is remembering that a GPS primarily navigates TO a fix or waypoint. When we have a flight plan it will sequence from one fix to the next (unless we

suspend that sequencing, such as if we must hold).

Look at the flight plan for a flight from KGON to KOWD via ORW and WOONS. While we're in flight and the GPS is taking us from ORW to WOONS, we decide we want the RNAV Rwy 35 approach, starting at DODNE.

Loading the approach will put the approach procedure and its waypoints at the end of the flight plan, after the destination airport—but the GPS will still be navigating us to WOONS and from there to KOWD. This is correct because we haven't been cleared for the approach. The GPS will sequence from waypoint to waypoint to the destination airport, as cleared. This approach is not active. You can tell that because the magenta arrow to the left of the flight plan waypoints is above the approach procedure title.

When ATC clears us to DODNE, we should activate the approach. We can do this by selecting "Activate approach" or by entering direct-to the initial approach fix. These do exactly the same thing. If ATC clears us to an intermediate fix, we can use direct-to that fix, which will also activate the approach inbound from the IF. If ATC vectors us for the approach, we can activate vectors-to-final or a leg of the approach we expect to intercept.

In all of these cases, the approach is now active—there's no need to later "activate" the approach. How do you know it's active? Because the magenta arrow for direct-to or an active leg appears *below* the approach procedure title.

So to avoid any confusion, don't activate an approach until ATC clears you to either the initial fix, any fix inside the IAF or for vectors-to-final—and don't get confused thinking you have to reactivate it if you used a direct-to for getting established on the approach."





## **November 2021 Board Meeting Minutes.**

	Olds F	orge Flyers	s - Meeting Minu	tes			
Date:	10/21/2021	Time: 6:00	Location:	Zoom Conf	Call		
Attenda	ince:		<u>'</u>				
	Board Member	Attended	Member / Guest In	Attendance	Member		
Larry Bo	orton - President	×	Clark Radcliffe		×		
DE STAND BATHS	st - Vice President	×					
	Steve Harsh - Treasurer						
	olby - Secretary	×					
	kendale (2 yr)	X					
	oucke (2 yr)	×					
Chet Da		×					
Frank Ed	5-19-19-19-19-19-19-19-19-19-19-19-19-19-	×					
John Yu	rkon	×					
4.CEL 15	A AND DECCHESTOR						
	A AND DISCUSSION:	<b></b>					
1	Call to Order (President or Execution Meeting called to order by Larry B. at 0						
2	Additions to Agenda: (Board)	5.00 pm					
	None at this time.						
3	Approval of Minutes of Previous	Meeting: (Colby)					
1000		September minutes submitted via e-mail by Steve C. for Board review.					
	Motion to approve the minutes by John			on.			
4	4 Review and Approval of Treasurers Report: (Harsh)						
	Treasurer's report sent out previously via email. Larry B. summarized the report as follows. Finances are looking good. Income is meeting budget. Operating expenses are less due to lower fuel and annual inspections. Question by Dick B. regarding the required contingency funds and the possibility of upgrading the Archer autopilot and the Skyhawk Nav/Com. Chet D. to follow up with Bear for a GTN650Xi quote in the Skyhawk.						
	1	ove by Steve C., 2nd by Dick B., motion approved without opposition.					
	Motion to approve by Steve C., 2nd by	Dick B., motion appro	oved without opposition.				
5	Motion to approve by Steve C., 2nd by  Maintenance Report: (Dawson)	Dick B., motion appro	oved without opposition.				
5	Maintenance Report: (Dawson)  Archer - GPS updated thru Nov 4th, W movement of the beacon power supply improvement ideas. Clark R. had issue Skyhawk - GPS updated thru Nov 4th,	ill try another fix for t No issues found to e s with the radio recept oil change next week.	he interior trim screw. AI is adju xplain the poor radio reception. C tion at lower altitudes, better at hi Chet D. also noted concern with	Chet to follow up with gher altitudes. the Skyhawk interior	Beacon for as noted from sitting		
5	Maintenance Report: (Dawson)  Archer - GPS updated thru Nov 4th, W movement of the beacon power supply improvement ideas. Clark R. had issue Skyhawk - GPS updated thru Nov 4th, in the back seat. Clark R. noted that if large quantity of items stored there.	ill try another fix for t No issues found to e s with the radio recept oil change next week. an interior upgrade is	he interior trim screw. AI is adju xplain the poor radio reception. C tion at lower altitudes, better at hi Chet D. also noted concern with undertaken, the seat back pocket	Chet to follow up with gher altitudes. the Skyhawk interior is could be fashioned to	Beacon for as noted from sitting		
	Maintenance Report: (Dawson)  Archer - GPS updated thru Nov 4th, W movement of the beacon power supply improvement ideas. Clark R. had issue Skyhawk - GPS updated thru Nov 4th, in the back seat. Clark R. noted that if large quantity of items stored there.  Motion to approve the Maintenance reports.	ill try another fix for t No issues found to e s with the radio recept oil change next week. an interior upgrade is	he interior trim screw. AI is adju xplain the poor radio reception. C tion at lower altitudes, better at hi Chet D. also noted concern with undertaken, the seat back pocket	Chet to follow up with gher altitudes. the Skyhawk interior is could be fashioned to	Beacon for as noted from sitting		
5	Maintenance Report: (Dawson)  Archer - GPS updated thru Nov 4th, W movement of the beacon power supply improvement ideas. Clark R. had issue Skyhawk - GPS updated thru Nov 4th, in the back seat. Clark R. noted that if large quantity of items stored there.  Motion to approve the Maintenance reports	ill try another fix for to No issues found to eas with the radio receptorial change next week. Year interior upgrade is port by Dick B., 2nd by	he interior trim screw. AI is adjust a plain the poor radio reception. On at lower altitudes, better at his Chet D. also noted concern with undertaken, the seat back pocket by Dave O., motion approved with	Chet to follow up with gher altitudes.  the Skyhawk interior is could be fashioned to but opposition.	Beacon for as noted from sitting accomodate the		
	Maintenance Report: (Dawson)  Archer - GPS updated thru Nov 4th, W movement of the beacon power supply improvement ideas. Clark R. had issue Skyhawk - GPS updated thru Nov 4th, in the back seat. Clark R. noted that if large quantity of items stored there.  Motion to approve the Maintenance reports.	ill try another fix for to No issues found to eas with the radio reception oil change next week. Year interior upgrade is port by Dick B., 2nd by rsuing a candidate that	he interior trim screw. AI is adjust a plain the poor radio reception. Option at lower altitudes, better at his Chet D. also noted concern with undertaken, the seat back pocket by Dave O., motion approved without it is interested in joining. Dick B.	the to follow up with gher altitudes.  the Skyhawk interior is could be fashioned to but opposition.	Beacon for as noted from sitting to accommodate the archased the Pilot's		
6	Maintenance Report: (Dawson)  Archer - GPS updated thru Nov 4th, W movement of the beacon power supply improvement ideas. Clark R. had issue Skyhawk - GPS updated thru Nov 4th, in the back seat. Clark R. noted that if large quantity of items stored there.  Motion to approve the Maintenance reports  Membership (Best) - Dick B. is still put Workshop manual for the GTN650Xi.	ill try another fix for to No issues found to eas with the radio reception oil change next week. Year interior upgrade is port by Dick B., 2nd by rsuing a candidate that	he interior trim screw. AI is adjust a plain the poor radio reception. Option at lower altitudes, better at his Chet D. also noted concern with undertaken, the seat back pocket by Dave O., motion approved without it is interested in joining. Dick B.	the to follow up with gher altitudes.  the Skyhawk interior is could be fashioned to but opposition.	Beacon for as noted from sitting to accommodate the archased the Pilot's		
6 a	Maintenance Report: (Dawson)  Archer - GPS updated thru Nov 4th, W movement of the beacon power supply improvement ideas. Clark R. had issue Skyhawk - GPS updated thru Nov 4th, in the back seat. Clark R. noted that if large quantity of items stored there.  Motion to approve the Maintenance reports  Membership (Best) - Dick B. is still pu Workshop manual for the GTN650Xi. the office computer.	ill try another fix for the No issues found to east with the radio reception oil change next week. It is an interior upgrade is port by Dick B., 2nd by resuing a candidate that Lots of good information.	he interior trim screw. AI is adjusting the poor radio reception. Option at lower altitudes, better at his Chet D. also noted concern with undertaken, the seat back pocket by Dave O., motion approved without it is interested in joining. Dick B. ion and features revealed. Dick I	the to follow up with gher altitudes.  the Skyhawk interior is could be fashioned to but opposition.	Beacon for as noted from sitting to accommodate the archased the Pilot's		

## **November 2021 Board Meeting Minutes.**

a	Board Meeting - Next is scheduled for November 18th. Question regarding when we will start meeting in personwill plan to start meeting in person in January and will monitor the Covid situation between now and then.				
ь	<ul> <li>b1) POH - The condition of the manuals is not satisfactory. Mark C. is proposing we obtain new binders for the two POH's to better protect the content before we start losing the pages.</li> <li>b2) Mark C. donated his PTT switch to the Skyhawk. Please make sure it does not leave the aircraft.</li> <li>b3) Mark C. also asked if we could have a spare office key available with AvFlight. Dick B. to follow up with a key.</li> </ul>				
9	Discussion Of Flying Experiences				
	Carburetor icing - Discussion of member's experiences with carb icing and how to manage it with the two aircraft. The Skyhawk and the Archer POH's have different requirements for the use of carb heat. Be sure to review each aircraft for the specifics.  John Y. shared that he is in the process of buying an airplanea yellow one with a Z stripe!! Congrats Jon!				
10	Adjournment:				
	Larry B. called for a motion to adjourn. Dick B. made the motion to adjourn, 2nd by Mark C., motion approved without opposition. Meeting concluded at 6:53 pm. Thanks to John Y. for the use of his Zoom account.				

## Olds Forge Flight Instructor Contact Information

Mark Coucke	517-719-9061	mdcoucke@gmail.com
Adlay Kejjan	517-899-0731	adlaykejjan@gmail.com
Pete Kamarainen	517-281-3899	pete@grandairaviation.com
Fred Moore	517-230-7918	fredmoore48842@aol.com

## The Latest TSA Badging Procedures

The badging office has rescinded its relaxed Covid 19 procedures and we are once again required to review your *completed* application before signing it. So.....no more emailing to you already signed forms. Remember — you can apply up to 60 days before your badge expires on **your birthday**. Yes, that's right, the office has asked us to clarify when your badge expires: **on your actual birthday**, not the end of the month of your birthday. Also, effective July 1, there will be a **\$20 renewal fee** for badge renewals. If you want Dick to sign your badge application, please get your form from him with his information already filled out so he doesn't have to repeatedly fill in that information. dick@richard-best.com Dick will be available to sign your app at any board meeting or scheduled event. Signed apps are valid for two weeks and may be used up to 60 days before badge expiration.

## **December 2021 Board Meeting Minutes.**

		Olds Forge	Flyers	- Meeting Min	utes	
Date:	12/16/2021	Time:	6:00	Location:	Zoom Conf	Call
Attendo	ance:					
	Board	Member	Attended	Member / Guest I	n Attendance	Member
Larry Bo	orton - President		×			
Dick Best - Vice President		Х				
Steve H	larsh - Treasurei	•	X			
Steve C	olby - Secretary		X			
Dave Ox	xendale (2 yr)		X			
Mark Co	oucke (2 yr)		X			
Chet Do	iwson		Х			
Frank E	astman		Х			
John Yu	ırkon		×			
AGEND	A AND DISCUS	SION:				
1	Call to Order	(President or Executive N	lember)			
	Meeting called to	order by Larry B. at 6:00 pm				
2		igenda: (Board)				
	Chet D. added the	e topic of internet access in the	office.			
3	Approval of M	inutes of Previous Meetin	g: (Colby)			
	November minutes submitted via e-mail by Steve C. for Board review.					
	Motion to approve the minutes by John Y., 2nd by Chet D. Motion approved without opposition.					
4	Review and Ap	proval of Treasurers Rep	ort: (Harsh)			
	Income running as expected, expenses running less (fuel & annuals). Predicting \$9-10k surplus at year end provided no unexpected					
	expenses arise.		620	3 000 20		
	Motion to approve by Dick B., 2nd by Steve C., motion approved without opposition.					
5	Maintenance Report: (Dawson)					
	GPS's updated to December 30th for both aircraft.  Skyhawk - a power cord is in the Skyhawk hanger (unheated) to plug in the Tannis heater. Make sure you remind AvFlight personne plug it in when the aircraft is parked in the hanger. If you find it not plugged in, please notify AvFlight and Chet.  Archer - Les feels that the heated hanger should not require plugging in the Tannis heater on the Archer. Chet will review the timer of the heater to understand its operation. Chet reviewed a cold weather prime procedure for the Archer. Also - if AvFlight is going to p position the airplane for you prior to your arrival, we should ask them to plug the Tannis heater in.  Dick B. read some information from Tannis about temperatures and blanketing the engine and plugging the cowls.  John Y. read online information regarding the time benefits of the heatertwo hours for a 40 degree gain, maximum benefit in six hours to approve the Maintenance Report by Steve C., 2nd by Dick B., motion approved without opposition					review the timer on light is going to pre-
6	Committee Reports					
	Dick B. was contr Dick B. has anoth	st) - Jim V. contacted Dick B. a acted by a former Spartan Wing her person that will be joining that date is awaiting FAA Medical a	gs member, wil nis spring and l	l be submitting an application he has another interested cano	shortly. lidate as well.	oved this action.
7	Old Business:	1000	1965 - 19		Bristell	915 Turbo

## **December 2021 Board Meeting Minutes.**

Archer Autopilot Upgrade - Motion by Dick B. to un-table the previous month's motion postponing the decision to move ahead the Archer Autopilot with the Auto Trim feature, 2nd by Chet D. Motion carried without opposition. Chet D. reviewed an update to the Archer GFC500 with Auto Trim quote. Steve H. proposed an amendment to the motion to include the upgrade to the Skyhawk with the GTN650Xi, 2nd by Dick B. This results in a motion to move forward with the installation of the GFC500 with Auto Trim in the Archer and the installation of the GTN650Xi in the Skyhawk through Beacon Aviation. The Archer will be first followed by the Skyhawk providing satisfactory results with the Archer installation. \$13,300 for the Archer and \$15125 for the Skyhawk. Motion carries without opposition. Chet D. to talk with Beacon tomorrow to discuss deposit and timing. Steve H. asked to be advised of that discussion to maintain appropriate fund management in the Club.

Skyhawk GTN650Xi Upgrade - See above discussion.

#### 8 New Business:

α

b

January 20th Board Meeting - Larry B. proposed continuing the Zoom meetings for now. A possible hybrid meeting may be in the wings with some members meeting at AvFlight.

Internet Access in the Office - The internet access has been frustrating for the GPS upgrades. A Club member with IT experience noted that the internet router in use byAvFlight is old. Chet D. discussed a joint venture with AvFlight on replacing the router, that discussion is continuing. Mark C. asked if a Cat5 cable could be ran through the ceiling to our office.

#### 9 Discussion Of Flying Experiences

Chet D. reported that he and John Y. took the Skyhawk up and checked the engine speed with a mobile tachometer. Chet D. will publish the results to the membership. 2500 indicated is 2400 actual. Mark C. asked if we could get a quote from Beacon for a digital engine monitoring system for the aircraft. Chet D. will ask.

John Y, stated that AvFlight has their annual Christmas party on Wednesday the 22nd from 11:00-1:30.

#### 10 Adjournment:

Larry B. called for a motion to adjourn. Steve C. made the motion to adjourn, 2nd by Dick B., motion approved without opposition. Meeting concluded at 7:11 pm. Thanks to Steve H. for the use of his Zoom account.

## **Guess the Flight Deck**



## **Monthly Hours Flown Report:**

Skyhawk \$ 90 / hr. Archer \$ 105 / hr. 2021 2020 2021 2020 Year-to-date 229.0 71.5 125.1 62.2 Total Nov-Dec 16.2 16.2 17.5 10.7 **TOTAL** 245.2 87.7 72.9 143.6

**COMBINED 2021 HOURS: 388.8** 

The club flew 228 combined hours more in 2021 than we did in 2020. Not surprising with Covid 19 in 2020. We also flew 100 combined hours more than in 2019 and 138 hours more than in 2018.

There's lots to fly to in Michigan, even in winter. Great Lakes shoreline ice buildups are always fascinating from the air. Mackinac Island is less than a two hour flight. Or make a weekend out of an adventure to the Air Force Museum in Dayton Ohio. Sign up with socialflight.com for your customized weekly email listing of timely and interesting destinations. The kids will love the full motion simulators at the "Air Zoo" in Kalamazoo (KAZO). Check their web site. You can taxi right in to the museum's parking area. It's an extremely good museum that amazingly even has an SR-71. Traverse City (KTVC) has a courtesy car available. Many great restaurants. Grand Traverse Bay is beautiful from the air. Or how about a Macinac Island weekend-fly in and skip the ferry. In the U.P., there's the Soo Locks, Pictured Rocks and Marquette. There's lots of great destinations and plenty of sightseeing in the mitten. And you can do it all from the air. You've got a pilot license—USE IT!!!

#### FLYING IS FUN!

## **Maintenance Summary**

**Maintenance Issues:** 

Notify Chet: 517-449-2182 chet777@comcast.net

517-339-3727

Skyhawk: GPS updated.

Annual Due: 2/12/2022 Hours flown since last annual: 157.9

Archer: GPS updated.

Annual Due: 3/12/2022 Hours flown since last annual: 171.9

USE Phillips 20W 50 OIL ALL YEAR!

**Please record oil usage accurately,** and make sure you have enough oil in the plane for your cross-country flight. GPS cards in each plane include expiration date.

Thanks, Chet, and Stevo!

### **BOARD MEETING**

Thursday, January 20th, 6 PM (1800)
ZOOM Meeting link will be emailed
All members encouraged to attend

## Financial Report

### **OLDS FORGE FLYERS, INC**

**Profit & Loss Statement** 

January 1 - November 30, 2021

Archer Hr =	141.1	Skyhawk Hr =	273.0
		Actual	Budget
OPERATING INCO	ME:		
Aircraft Income	•	\$33,271	\$39,385
Initiation Fees		\$5,050	\$1,900
Membership Du	ues	\$29,375	\$26,180
Interest		\$1	\$0
Other Misc. Inc	ome	\$70	\$0
TOTAL	INCOME	\$67,767	\$67,465
OPERATING EXP	ENSES:		
Variable Costs	s:		
Improvements,	Archer & Skyhawk	\$2,070	\$2,071
Engine Depletion	on, Archer	\$2,251	\$2,251
Engine Depletion	on, Skyhawk	\$3,890	\$3,890
Fuel, Archer		\$4,312	\$5,983
Fuel, Skyhawk		\$6,923	\$9,405
Misc fuel & Oil		\$539	\$0
Maintenance, A	Archer*	\$1,952	\$4,784
Maintenance, S	Skyhawk*	\$2,612	\$7,233
Maintenance, C	Other	\$331	\$0
Total V	ariable Cost	\$24,880	\$35,616
Fixed Costs:			
Office and Serv	ice Fees	\$1,770	\$2,198
Operations Cos	sts	\$19,951	\$20,707
Total F	ixed Costs	\$21,721	\$22,904
Misc. Cost		\$0	\$300
TOTAL	EXPENSES	\$46,601	\$58,820
NET O	PERATING INCOME	\$21,166	\$8,645
Contingency Fu	und (equity fees)	\$5,050	\$1,900
NET A	FTER CONTIN. FUN	D \$16,116	\$6,745

- \* Archer Annual (Budget = \$2,,800; Actual = \$1,572)
- \* Skyhawk Annual (Budget = \$2,200; Actual = \$1,556)

